



FAG

Service Info



ABS sensor ring available as an accessory

Manufacturers:	DAF SAF
Part no.:	
Wheel bearing (RIU):	566074.H195 566834.H195 570530.H195
ABS ring:	434 0497 10 434 0498 10



ABS sensor ring 434 0497 10 with special fitting tool

When changing a wheel bearing on vehicles equipped with ABS, it is not strictly necessary to replace the sensor ring. However, if the ABS sensor ring is damaged, it must be replaced.

As the Repair Insert Units (RIU) listed above can also be installed on vehicles not equipped with an ABS, Schaeffler Automotive Aftermarket does not include an ABS sensor ring in the pack.

If a repair is being performed to a wheel bearing on a vehicle equipped with ABS - and the sensor ring is therefore required - it can be ordered separately as an accessory. ABS sensor rings are listed as an accessory in both the printed and digital catalogues.



ABS sensor ring 434 0498 10

ABS sensor ring	Repair Insert Unit (RIU)
434 0497 10	570530.H195
434 0498 10	566074.H195 566834.H195

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264*

Fax: +44 (0) 1432 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.co.uk

* Calls from within the UK 08457 001100



FAG



SCHAEFFLER
AUTOMOTIVE AFTERMARKET