



Service Info



Design change

affecting tensioning pulley 534 0168 10

Manufacturers: Land Rover, MG, Rover

Model:

Land Rover: Freelander

MG: ZR, ZS

Rover: 25

Engine:

Land Rover: 1.8

MG: 1.4, 1.6

Rover: 1.2

Part no.: 534 0168 10

OE number: PQG100180
PQG100180A
QVU 10022



Figure 1: Previous design (left) and new design (right)

As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulley with part number 534 0168 10.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

This Service Information sheet shows the visual features of the previous version (Figure 1, left) and the new version (Figure 1, right).

Note the specifications of the vehicle manufacturer!

During the transition period, we may have mixed stocks of both types.

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
info@luk-as.co.uk
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

