



Service Info



Change affecting tensioning pulley 531 0813 10

Manufacturers: Ford, Mazda, Volvo

Models:

Ford: B-Max, C-Max, Grand C-Max, Fiesta, Focus, Fusion, Mondeo

Mazda: 2

Volvo: C30, S40, V50

Year of manufacture:

From 2005

Engines:

1,25, 1,4, 1,6 16V

Part no.:

531 0813 10
530 0495 10 (KIT)
530 0495 30 (KIT+water pump)

OE number:

Ford: 1376164
5M5G-6K254-AB

Mazda: C401-12-500

Volvo: 30750905



Figure 1: Left: the previous version. Right: the new version

As part of our continuous efforts to improve our products, modifications have been made to tensioning pulley 531 0813 10 and the associated fixing bolt.

This Service Information sheet shows the visual features of the previous version (Figure 1, left) and the new version (Figure 1, right).

During the transition period, we may have mixed stocks of the different types.

Both versions meet the technical specifications and can be used without restrictions on the specified vehicles.

When installing the modified tensioning pulley, the enclosed fixing bolt M8x47 (torque value 25 Nm) must be used. As the screw hole has changed, it is not permitted to use mixed components.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
hfd-info@schaeffler.com
www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

