

# VISUAL DIFFERENCES IN ROCKER ARM 235404

TECHNICAL INFO NO. 1089

## VEHICLE MANUFACTURER / MODELS:

<b>Audi</b>	A1, A3
<b>Seat</b>	Altea, Ibiza, Leon
<b>Skoda</b>	Fabia, Octavia, Superb
<b>VW</b>	Eos, Golf IV, Golf Plus, Golf V, Golf VI, Jetta III, Passat (C3_), Polo (6R_), Polo (9N_)

## APPLIES TO ENGINES:

1.4 FSI, 1.4 TSI, 1.4 TFSI, 1.6 16V, 1.6 FSI

## APPLIES TO PART NO.:

RUVILLE-No.	OE-No.
235404	036 109 411 E 036 109 411 G 036 109 411 H 036 109 411 J

### IMPORTANT NOTE!

**Always replace rocker arms in sets!** In the event of a fault in one or more rocker arms, all of the engine rocker arms should be replaced. To avoid multiple repairs and increased costs, always replace the rocker arm and the valve clearance adjustment element at the same time during maintenance. Please, check the condition of the camshaft in the course of the repair and if necessary change it.

Note the specifications of the vehicle manufacturer!



Figure 1: Version 1



Figure 2: Version 2

When replacing rocker arm 235404, either of the versions shown in Figure 1 and Figure 2 may be installed in the vehicle.

RUVILLE supplies the rocker arm version shown in Figure 1.



### INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de). Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.