

CIRCLIPS MADE OF POLYAMIDE FOR AXIAL JOINTS

TECHNICAL INFORMATION NO.: 1095

AFFECTED VEHICLES:

Renault	Clio II+III, Kangoo
Nissan	Kubistar, Mikra (...K12)

AFFECTED ARTICLES:

Ruville No.	OE No.
915597	7701472120 4852100QAG
915582	7701475841

INSTALLATION INSTRUCTIONS:

- Replace the circlip every time after it has been removed.
- Allocation according to the colour of the ring

IMPORTANT NOTE:

Note the specifications of the vehicle manufacturer!

Some models by Renault and Nissan are fitted with an OE circlip consisting of a polyamide ring to retain the axial joint. The polyamide ring gets squashed during installation and therefore always has to be replaced every time it is removed.

Furthermore, replacement of the circlip is a mandatory OE requirement.

As your service partner, RUVILLE therefore includes all corresponding polyamide rings with the respective axial joints.

The circlips are allocated correctly according to the colour of the removed ring.



Fig. 1: Axial joint and circlips 915597



INFORMATION

Corresponding spare parts can be found in our online catalogue at www.ruville.de. Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.