

VISUAL DIFFERENCES BETWEEN THE TENSIONER PULLEYS OF THE VW- GROUP

TECHNICAL INFO NO. 1024

VEHICLE MANUFACTURER/MODELS:

Audi	A3, A4, A6, TT
Seat	Altea, Cordoba, Ibiza III, Inca, Leon, Toledo III
Škoda	Fabia, Octavia
VW	Bora, Caddy, Eos, Golf IV, Golf V, Jetta III, New Beetle, Polo, Passat, Touran

APPLIES TO ENGINES:

1.9 TDI, 1.9 SDI, 2.0 FSI, 2.0 TFSI

APPLIES TO PART NO.:

RUVILLE-No.:	OE-No.:
55736	028 109 243 K
55491	038 109 243 N
55769	06D 109 243
55772	06D 109 243 B

IMPORTANT NOTE!

Note the specifications of the vehicle manufacturer!




Image 1: Improved race coating — item No. 55736 shown here as an example

As part of our continuous efforts to improve our products, the coating of the drive wheels on the specified tensioner pulleys has been modified. The new surface is more durable than the old design.

During the transitional phase, we may have mixed stocks of both designs. Both versions fulfil the relevant technical specifications and can be used without restrictions.



INFORMATION

The corresponding spare parts can be found in our online catalogue at www.ruville.de

EGON VON RUVILLE GmbH

Billbrookdeich 112 • 22113 Hamburg • Germany

Tel.: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199

info@ruville.de • www.ruville.de