

# VISUAL DIFFERENCES IN OVER-RUNNING ALTERNATOR PULLEY 59941

TECHNICAL INFO NO. 1091

## VEHICLE MANUFACTURER / MODELS:

**Toyota** | Hilux, Fortuner

## APPLIES TO ENGINES:

2.5 D-4D, 3.0 D4-D

## APPLIES TO PART NO.:

RUVILLE-No.	OE-No.
59941	27415-0L040

### IMPORTANT NOTE!

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Note the specifications of the vehicle manufacturer!

As part of our continuous efforts to improve our products, modifications have been made to the over-running alternator pulley with part number 59941.

This Technical Information sheet shows the visual features of the previous version (Figure 1) and the new version (Figure 2).

During the changeover period, it is possible for mixed stocks of both versions to occur. Both versions comply with the technical requirements and can be used without restrictions for the vehicles stated in the catalogues.



Figure 1: Previous design



Figure 2: New design



### INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de). Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.

 **RUVILLE**  
YOUR PARTNER