



FAG Service Info



Installation instructions – Renault Laguna II

Correct installation of rear hub carrier bush

Manufacturer: Renault

Models: Laguna II
Laguna II Grandtour

Part numbers: 830 003 630
(829 049 310, 829 049 410)

OE numbers: 7701209534
(8200427868, 8200427869)

For current listing refer to catalogue media

The repair set 830 003 630 comprises two different rear hub carrier bushes (829 049 410 and 829 049 310), which absolutely must be installed according to OE specifications. So please observe Figure 1, which shows the correct installation position and orientation of the components. When repairing the hub carrier bushes they should always be replaced as a pair.




Fig. 1: Correct orientation of carrier bushes in the rear axle beam

Nr.	OE-numbers	FAG	Name
1	8200427869	829 049 410	Rear hub carrier bush (round hole)
2	8200427868	829 049 310	Rear hub carrier bush (elongated hole)
1+2	7701209534	830 003 630	Rear hub carrier bushes (pair)

Please observe the vehicle manufacturer specifications!

You want more? We can help!

Phone: +44 (0) 1432 264 264

Fax: +44 (0) 1432 375 760

aftermarket.uk@schaeffler.com

www.repxpert.co.uk