

Change to the appearance of deflecting pulley 532 0138 10

Vehicle Citroën, Fiat,
manufacturer: Lancia, Peugeot

Models:

Citroën: Evasion, Xantia, XM,
Xsara, ZX
Fiat: Ulysse
Lancia: Zeta
Peugeot: 306, 405, 406, 605, 806,
Expert

Engine: 1.6, 1.6i,
1.8, 1.8i, 1.8 ST,
2.0, 2.0i, 2.0 Turbo,
2.0i 16V

OE-No.:

Citroën: 5751.20
Fiat: 96 089 899 80
Lancia: 96 089 899 80
Peugeot: 5751.20

Item no.: 532 0138 10

As part of our continuous efforts to improve our products, changes have been made to the deflecting pulley, item no. 532 0138 10.

This Service Information sheet shows the visual features of the previous design and the new design.




Figure 1: 532 0138 10 - previous design

Key to figure 1:

1. Previous deflecting pulley design
2. Spacer
3. Screw




Figure 2: 532 0138 10 - new design

Key to figure 2:

4. Cardboard disk (screw locking device – must be removed before assembly)
5. New deflecting pulley design
6. Screw (integrated spacer)

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 05.2009

INA 0030

Technical subject to change

© 2009 Schaeffler Automotive Aftermarket oHG

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

