



Service Info



Modified timing belt KIT 530 0196 10

Manufacturers: Mitsubishi, Nissan, Opel, Renault, Vauxhall, Volvo

Model:

Mitsubishi: Carisma, Space Star

Nissan: Interstar, Primastar

Opel/Vauxhall: Movano, Vivaro

Renault: Espace IV, Laguna I, Laguna II, Master II, Traffic II

Volvo: S40, V40

Engine: 1.9 D

Part no.: 530 0196 10

OE number:

Mitsubishi: MW 3062 1589

Nissan: 16806-00QAF

16806-00QAJ

16806-00Q0A

Opel/Vauxhall: 91158706

Renault: 77 01 477 048

Volvo: 30777408

31272975



Image 1: 530 0196 10 - INA repair KIT for the timing gear with timing belt 536 0278 10, tensioning pulley 533 0087 20 and crankshaft screw

When replacing the timing belt on the Volvo models listed above, the vehicle manufacturer has specified that the crankshaft screw must always be replaced.

For this reason, the crankshaft screw is included in timing belt KIT 530 0196 10 (Image 1).

The other vehicle manufacturers listed do not have any specifications relating to this kind of change.

In principle, however, it is recommended that you install the supplied crankshaft screw here as well.

Replacing the crankshaft screw is specified by the vehicle manufacturer in the Volvo models listed.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

hfd-info@schaeffler.com

www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
AUTOMOTIVE AFTERMARKET

