



## Service Info



# Change affecting tensioning pulley 531 0813 10

Manufacturers: Ford, Mazda, Volvo

**Models:**

Ford: Fiesta, Focus, Mondeo

Mazda: 2

Volvo: C30, S40, V50

**Year of**

manufacture: From 2005

**Engine:**

1,25, 1,4, 1,6 16V

**Part no.:**

531 0813 10

**OE number:**

Ford: 1376164

5M5G-6K254-AB

Mazda: C401-12-500

Volvo: 30750905



Figure 1: Top: the two previous versions with red or black seal. Bottom: the new version

As part of our continuous efforts to improve our products, modifications have been made to tensioning pulley 531 0813 10 and the associated fixing bolt.

This Service Information sheet shows the visual features of the previous versions (Figure 1, top) and the new version (Figure 1, bottom).

During the transition period, we may have mixed stocks of the different types.

All three versions meet the technical specifications and can be used without restrictions on the specified vehicles.

When installing the modified tensioning pulley, the enclosed fixing bolt M8x46 must be used. As the screw hole has changed, it is not permitted to use mixed components.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under [www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com) or [www.RepXpert.com](http://www.RepXpert.com).

Phone: +44 (0) 14 32 264 264\*

Fax: +44 (0) 14 32 375 760

[hfd-info@schaeffler.com](mailto:hfd-info@schaeffler.com)

[www.schaeffler-aftermarket.com](http://www.schaeffler-aftermarket.com)

\* Calls from within the UK 08457 001100

**SCHAEFFLER**  
AUTOMOTIVE AFTERMARKET

