

# REPLACING TENSIONER LEVER 58853 IN 58916 FOR MERCEDES ACTROS

TECHNICAL INFO NO. 1025

## VEHICLE MANUFACTURER/MODELS:

Mercedes | Actros

## APPLIES TO ENGINES:

OM  
541.920, 541.921, 541.922, 541.923, 541.924, 541.925, 541.926,  
541.927, 541.941, 541.943, 541.944, 541.947, 542.920, 542.921,  
542.922, 542.925, 542.940, 542.960

## APPLIES TO PART NO.:

RUVILLE-No.:	OE-No.:
58853 (alt)	A 541 200 2470 (old)
58916 (neu)	A 541 200 2570 (new)

## IMPORTANT NOTE!

Note the specifications of the vehicle manufacturer!



Image 1: 58853 (replaced design)

Tensioner lever 58853 (image 1) is no longer available and has been replaced by item no. 58916 (image 2).



Image 2: 58916 (current design)

The fundamental differences between the two designs are a new deflecting pulley with improved running characteristics and a modified shield plate.



## INFORMATION

The corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de)

EGON VON RUVILLE GmbH

Billbrookdeich 112 • 22113 Hamburg • Germany

Tel.: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199

info@ruville.de • [www.ruville.de](http://www.ruville.de)