

DESIGN CHANGE AFFECTING TENSIONING PULLEY 55443

TECHNICAL INFO NO. 1027

VEHICLE MANUFACTURER/MODELS:

Audi	A3, A4
Seat	Alhambra, Altea, Altea XL, Cordoba, Ibiza III, Leon, Toledo II, Toledo III
Škoda	Fabia, Octavia, Superb
VW	Bora, Caddy III, Golf IV, Golf V, Golf VI, Jetta III, New Beetle, Passat, Polo, Sharan, Touran, Multivan/Transporter T5

APPLIES TO ENGINES:

1.6, 2.0, 2.0i

APPLIES TO PART NO.:

RUVILLE-No.:	OE-No.:
55443	06A 109 479 C (current) 06A 109 479 (replaced) 06A 109 479 A (replaced) 06A 109 479 B (replaced)

Due to the constant development of our products, the design of tensioning pulley 55443 has been changed.

IMPORTANT NOTE!

The special tool (OE no. T10020) for turning the eccentric is no longer needed.

Please use a 6 mm allen key.

Note the specifications of the vehicle manufacturer!

This Technical Information sheet shows the visible differences between the two versions from the front and back of each tensioning pulley.




Image 1: 55443 – previous design




Image 2: 55443 - new design

We may have mixed stocks during the transitional phase. Both tensioning pulleys meet the technical specifications and can be used without restrictions on the specified vehicles.



INFORMATION

The corresponding spare parts can be found in our online catalogue at www.ruville.de

EGON VON RUVILLE GmbH

Billbrookdeich 112 • 22113 Hamburg • Germany

Tel.: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199

info@ruville.de • www.ruville.de