

REPAIR SOLUTION FOR THE OPEL WATER PUMP

TECHNICAL INFO NO. 1045

VEHICLE MANUFACTURER / MODEL:

Opel | Agila 1.0, Astra G 1.2, Astra H 1.4, Combo, Corsa C
Corsa D, Meriva, Tigra

AFFECTED ARTICLES:

No.	RUVILLE No.:	OE No.:
1	65381*	1334145
2	65384	1334145

INFORMATION

We recommend the small repair solution if the temperature sensor can be dismantled and is technically in order.

We recommend the large repair solution when the abovementioned points do not apply.

*Contents differ from OE

IMPORTANT NOTE!

When replacing the water pump, the cooling system must be drained completely, cleaned if necessary and filled with new coolant.

Please comply with the instructions issued by the vehicle manufacturer!

In view of the differing requirements in the market, Ruville offers two repair solutions for the OPEL water pump OE No. 1334145.

1. "Small" repair solution (Article No.: 65381)

Pump without temperature sensor




Fig. 1: 65381 (without temperature sensor)

2. "Large" repair solution (Article No.: 65384)

Pump with temperature sensor




Fig. 2: 65384 (with temperature sensor)



INFORMATION

Corresponding spare parts can be found in our online catalogue at www.ruville.de

EGON VON RUVILLE GMBH

Billbrookdeich 112 • 22113 Hamburg • Germany

Phone: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199

info@ruville.de • www.ruville.de

RUVILLE
YOUR PARTNER