

MERCEDES WATER PUMP WITH 2 THERMOSTATS

TECHNICAL INFO NO. 1054

VEHICLE MANUFACTURER/MODELS:

Mercedes	Actros 1831, 2031 Actros MP2 / MP3, without retarder MK 1417, 1717, 814, 817
-----------------	--

APPLIES TO PART NO.:

No.	RUVILLE-No.	OE-No.
1	65135	A5422001501
2	65135S (new)	A5422001501

CONTENTS 65135 S:

1 x water pump
2 x thermostats (OE No. A0052032675)
4 x seals

IMPORTANT NOTE!

When the water pump is replaced, the coolant must always be changed and the cooling circuit flushed. The chosen coolant must have been given approval by the relevant vehicle manufacturer.

Please comply with the instructions issued by the vehicle manufacturer!

With immediate effect, Ruville now offers an additional repair solution for the stated applications. The repair solution includes not only the water pump with the four necessary seals but also both thermostats (83 °C).

Advantages of the large repair solution:

- optimises ordering costs
- reduces standstill times; reduces repair costs in the long run, with installation time of approx. 2 hours only once

1. „Small“ repair solution (Article No. 65135)

without thermostats




Figure 1: Water pump 65135 (without thermostats)

2. „Large“ repair solution (Article No.: 65135S)

with 2 thermostats (83°C)




Figure 2: Water pump 65135S (with thermostats)



INFORMATION

Please take note of our Ruville catalogue together with our HDV parts database at www.ruville.de

EGON VON RUVILLE GmbH

Billbrookdeich 112 • 22113 Hamburg • Germany
Tel.: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199
info@ruville.de • www.ruville.de

RUVILLE
YOUR PARTNER