

# MERCEDES WATER PUMP WITH 2 THERMOSTATS 65136S

TECHNICAL INFO NO. 1055

## VEHICLE MANUFACTURER / MODEL:

<b>Mercedes</b>	Actros 1831, 2031 Actros MP2 / MP3, with retarder MK 1417, 1717, 814, 817
-----------------	---

## AFFECTED ARTICLES:

No.	RUVILLE No.:	OE No.:
1	65136	A5422002001
2	65136S (new)	A5422002001

## CONTENTS 65136 S:

1 x water pump  
2 x thermostats (OE No.: A0052032675)  
5 x gaskets

### IMPORTANT NOTE!

When replacing the water pump, always change the coolant and purge the coolant circuit. The used coolant must be approved by the relevant vehicle manufacturer.

Please comply with the instructions issued by the vehicle manufacturer!

With immediate effect, Ruville offers an additional repair solution for the applications named here. The solution consists of the water pump together with the five necessary gaskets and both thermostats (83°C).

### Advantages of the large repair solution:

- Optimised ordering costs
- Reduced downtimes and lower long-term repair costs as the installation time of approx. 2 hours is only incurred once.

### 1. "Small" repair solution (Article No.: 65136) without thermostats



Fig. 1: Water pump 65136 (without thermostats)

### 2. "Large" repair solution (Article No.: 65136S) with 2 thermostats (83°C)



Fig. 2: Water pump 65136S (with thermostats)



### INFORMATION

Please also refer to our Ruville catalogue and our HDV parts database on [www.ruville.de](http://www.ruville.de)

EGON VON RUVILLE GMBH

Billbrookdeich 112 • 22113 Hamburg • Germany  
Phone: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199  
[info@ruville.de](mailto:info@ruville.de) • [www.ruville.de](http://www.ruville.de)

 **RUVILLE**  
YOUR PARTNER