

# DESIGN CHANGE

## AFFECTING TENSIONING PULLEY 56135

TECHNICAL INFO NO. 1092

### VEHICLE MANUFACTURER / MODELS:

Land Rover	Freelander
MG	ZR, ZS
Rover	25

### APPLIES TO ENGINES:

Land Rover	1.8
MG	1.4, 1.6
Rover	1.2

### APPLIES TO PART NO.:

RUVILLE-No.	OE-No.
56135	PQG100180
	PQG100180A
	QVU 10022


As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulley with part number 56135.

This Technical Information sheet shows the visual features of the previous version (Figure 1, left) and the new version (Figure 1, right).

During the transition period, we may have mixed stocks of both types.

### IMPORTANT NOTE!

Note the specifications of the vehicle manufacturer!



**Figure 1:** Previous design (left),  
and new design (right)



### INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de). Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.