

# REPLACEMENT OF TENSIONER AND VIBRATION DAMPER

TECHNICAL INFO NO. 1098

## VEHICLE MANUFACTURER:

Audi, Seat, Škoda, VW

## APPLIES TO ENGINES:

AWT, AWM, ALT, AVJ, AMB, BFB, BEX, BKB, CFMA

## APPLIES TO PART NO.:

RUVILLE-No. replaced	RUVILLE-No. new
55496	
55712	5636450 (Set)
5549651	
5549671	5636471 (Kit)
55496711	56364712 (Water pump kit)
55496712	56364711 (Water pump kit)

## IMPORTANT NOTE!

The use of mixed components is not permitted, as the components are adapted to one another and only ensure the correct belt tension when used together.

Note the specifications of the vehicle manufacturer!

In the vehicles listed above, vibration damper 55712 (Image 1, left) and tensioner 55496 (Image 1, right) have been replaced with Kit 5636471 (Image 2, left) and Set 5636450 (Image 2, right).

The new components differ not only in terms of their appearance but also in terms of their functionality. With the old design, the vibration damper, in addition to the tensioner, took on part of the belt tensioning function.

The new deflecting pulley with holder 56365 only has a deflecting function. The belt tension and damping is carried out by tensioner 56364 only.



Image 1: Vibration damper 55712 (left), tensioner 55496 (right)



Image 2: Kit 5636471 (left), Set 5636450 (right)



## INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de). Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.

