

# FITTING INSTRUCTIONS FOR FRONT WHEEL BEARING SEALING RING

TECHNICAL INFO NO. 2003

## MANUFACTURER/MODELS:

<b>Audi</b>	A2 (8Z0)
<b>Seat</b>	Cordoba (6L2), Ibiza (6L1)
<b>Škoda</b>	Fabia (6Y2, 6Y3, 6Y5), Roomster (5J)
<b>Volkswagen</b>	Polo (9N), Fox (5Z1)

## APPLIES TO PART NO.:

<b>RUVILLE-No.:</b>	<b>OE-No.:</b>
5732 (Kit)	14" 6Q0407623B / E (sealing ring)
7805 (Kit)	13" 6Q0407623C (sealing ring)
5453 (Kit)	

### IMPORTANT NOTE!

As soon as the sealing rings are available, they will be included in the respective kits. This will prevent the sealing rings being mixed up or incorrectly assigned.

Adhere to the vehicle manufacturer's specifications at all times!

Contamination on the inside of the wheel bearing can result in the failure of the wheel bearing. The wheel bearing seal is also affected by this, resulting in the damage mentioned above.

If you are replacing a wheel bearing, you must also use a sealing ring, which is placed on the drive shaft taper (see Fig. 1).




Figure 1: The sealing rings could differ in design and colour!



### INFORMATION

The corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de)

EGON VON RUVILLE GmbH

Billbrookdeich 112 • 22113 Hamburg • Germany

Tel.: +49 (0)40 73344-0 • Fax: +49 (0)40 73344-199

info@ruville.de • [www.ruville.de](http://www.ruville.de)