

Water pump repair kit for Citroën, Peugeot, Renault: 56643701

Technical info no. R205

Applies to make/model:

Citroën: Xantia I,II, 3.0 V6,
XM 3.0. V6 24V
Peugeot: 406 3.0 24V, 605 3.0 24V
Renault: Espace III 3.0 V6,
Laguna I,I 3.0 24V,
Safrane II 3.0 24V

Applies to part no.:

No.	RUVILLE ref.	OE ref.
1.	56643701	none
2.	56643 (new)	0829.C5, 9467557280
3.	65986 (old)	1201.A6, 9640344280
4.	65995	1201.F2, 9635018180

Applies to engines:

XFZ (ES9J4), L7X 727, 700, 701, 713

Important note:

Adhere to the manufacturer's specifications at all times!

A technical modification of the belt drive design on vehicles with V6 engine mandates that during normal water pump maintenance or toothed belt replacement, all belt drive components must be replaced!



This modification applies to models built before 12.1999.

Toothed belt tensioner (OE 0823.07, 9617067480) has been replaced by toothed belt tensioner 56643 (OE 0829.C5, 9467557280).

Water pump 65986 (OE 1201.A6, 9640344280) has been replaced by water pump 65995 (OE 1201.F2, 9635018180).

Explanation:

The remodelled toothed belt tensioner can not be attached to the old water pump 65986 (OE 1201.A6, 9640344280).

Remedy:

Installation of the water pump 65995 (OE 1201.F2, 9635018180). The water pump design conforms to the new design of the toothed belt tensioner 56643, which is why both parts must be replaced at once. These modifications are in line with the requirements of the OE manufacturers.

Parts included in the water pump repair kit 56643701:

New belt tensioner 56643 and water pump 65995 (including mounting parts).

The corresponding spare parts can be found in our online catalogue at www.ruville.de.