DIAMOND WASHER

FOR CRANKSHAFT VIBRATION DAMPER **TECHNICAL INFO NO. 1110**

VEHICLE MANUFACTURER / MODELS:

Audi A6

Volvo 850, S70, S80, V70 VW Crafter, LT, T4

APPLIES TO ENGINES:

2,5 TDI

APPL	IEC	TO	DΛ	DT	NO:
AFFL		$\mathbf{I} \mathbf{V}$	Γ		110

RUVILLE-No.	OE-No.		
5544570 (timing belt kit)	074 105 193 (VW)		
5547751 (pulley set)	862 79 35	(Volvo)	
5547771 (timing belt kit)			
5544652 (pulley set)			
5544672 (timing belt kit)			
5547752 (pulley set)			
5547772 (timing belt kit)			

IMPORTANT NOTE!

According to the vehicle manufacturer specifications, the central bolt on the crankshaft and the diamond washer (image 1) must be changed when replacing or disassembling the crankshaft vibration damper.

Note the specifications of the vehicle manufacturer!

The crankshaft vibration damper must be removed when replacing the timing belt on the vehicles listed above.

The central bolt on the crankshaft and the washer are included in the timing belt kits and timing belt sets listed above. The washer provided in these kits and sets has a special coating that works in conjunction with the central screw to prevent the vibration damper from working itself loose.



Image 1: crankshaft vibration damper with crankshaft central bolt and diamond washer



Corresponding spare parts can be found in our online catalogue at www.ruville.de. Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.

