



MEYLE®
Products

MEYLE No.

100 121 1009/HD
100 121 0010/HD
100 121 0074/HD

Reference No.

030 121 117 L
030 121 117 M
030 121 117 N

Thermostat housing

to fit

**Seat Ibiza II, Cordoba /
VW Polo (86C), Golf II/III, Jetta II, Vento (Jetta III)**



wie OE

Problem

Thermostat housing cracks and leaks

Effect

Coolant leaks out. Overheating of the motor is possible



Solution



- Increased plastic wall thickness
- Use of a higher temperature resistant plastic
- Replaced the self-tapping screws with brass threaded inserts and suitable screws to ensure safe change of the thermostat
- Improved design of critical radii
- Professional design of the O-ring layout
- Top quality O-rings and fastening material included

Advantage

Heavy duty version of the thermostat housing with longer life time and reduction of leakage risk

MEYLE - Miles in Motion

© MEYLE Products® - Wulf Gaertner Autoparts AG • L21.2004
Merkurring 111 • 22143 Hamburg • Germany
contact@meyle.com • www.meyle.com