

Changes to the tensioner pulley material of 531 0606 20

Manufacturer:

Iveco, Magirus-Deutz

Engine code: F2BE0682A

LuK AS Part No.: 531 0606 20

OE-No.: 500346227 (Plastic)
504106749 (Metal)



Fig. 1: Plastic Pulley





Fig. 2: Metal Pulley

The truck and bus manufacturer IVECO have replaced the belt tensioner with plastic pulley (OE-No. **500 346 227**) with a belt tensioner with a metal pulley (OE-No. **504 106 749**).

Due to this change in design, Schaeffler Automotive Aftermarket now offers both types of tensioner.

 Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at **www.Schaeffler-Aftermarket.com** or in RepXpert at **www.RepXpert.com**.

Issued 06.2008
INA 0020

Technical subject to change
© 2008 LuK-Aftermarket Service oHG

For further information:

Phone: +44 (0) 14 32 264 264*
Fax: +44 (0) 14 32 375 760
Info@LuK-AS.co.uk
www.Schaeffler-Aftermarket.com
* Calls from within the UK 08457 001100

