

SERVICE-INFO



Material change for tensioning pulley 531 0404 10

Vehicle

Manufacturer: Dacia, Nissan, Renault

Models:

Dacia: Sandero
Nissan: Kubistar
Renault: Clio II, Clio III, Clio Grandtour, Kangoo, Modus, Thalia, Twingo

Engines:

Dacia: 1.2 16V
Nissan: 1.2 16V
Renault: 1.2 16V

OE Nos.:

Nissan: 13077-00QAG (replaced)
13077-00QAL (current)
Renault: 77 11 115 394 (replaced)
82 00 035 827 (replaced)
82 00 103 069 (replaced)
82 00 454 895 (replaced)
82 00 704 394 (current)

Part No.: 531 0404 10



Image 1: Previous design made of metal



Image 2: New design made of plastic

The running surface of tensioning pulley 531 0404 10 has been changed from metal to plastic as part of our efforts to continuously develop our products.

It is possible that tensioning pulleys with metal pulleys as well as plastic pulleys will be delivered during the transition period.

Note:

Despite the variation in design, both tensioning pulleys can be used for the vehicles listed in the catalogues without restrictions.



Note the specifications of the vehicle manufacturer!

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or in RepXpert at www.RepXpert.com.

Issued 06.2011

INA 0077

Technical subject to change

© 2011 Schaeffler Automotive Aftermarket

Any reference to replacement part numbers for vehicle manufacturers is for comparison purposes only.

For further information:

Phone: +44 (0) 14 32 264 264*

Fax: +44 (0) 14 32 375 760

Info@LuK-AS.co.uk

www.Schaeffler-Aftermarket.com

* Calls from within the UK 08457 001100

