



Service Info





Design change

affecting tensioning pulley 531 0756 10

Manufacturers:

Citroen, Fiat, Ford, Lancia,

Peugeot, Volvo

Models:

C4, C5, C8, Jumpy Citroen: Fiat: Scudo, Ulysse

Ford: Focus C-Max, C-Max, Focus II,

Galaxy, Kuga, Mondeo IV, S-Max

Lancia:

Peugeot: 307, 308, 407, 508, 607, 807, Expert Volvo:

C30, S40, V40, V50, C70, V70, S80

2.0 HDI, 2.0 D Multijet, 2.0 JTD, **Engines:**

2.0 TDCi, 2.0 TDI

Part no.: 531 0756 10

OE numbers:

Citroen: 0829.A4 Fiat: 9464640480

Ford: 1231975 / 3M5Q-6B217-AA

Lancia: 9464640480 0829.A4 Peugeot: Volvo: 8653651



Figure 1: Previous design



Figure 2: New design



Figure 3: Previous design



Figure 4: New design

As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulley with part number 531 0756 10.

This Service Information sheet shows the visual features of the previous version (Figures 1 and 3) and the new version (Figures 2 and 4).

During the transition period, we may have mixed stocks of both types.

Both versions comply with the technical specifications and can be used without restrictions.

Note the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.



* Calls from within the UK 08457 001100





