



Service Info



Design change

affecting tensioning pulleys 531 0084 20 and 531 0103 20

Manufacturers: Audi
 Model: 80, 100, A4, A6, A8, Coupe, Cabriolet
 Year of manufacture: 1992 - 2000
 Engine: 2.4, 2.6, 2.8
 Part no.: 531 0084 20
 531 0103 20
 OE number: 078 109 243 C
 078 109 243 K




Figure 1: Previous design (left) and new design (right)

As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulleys with part number 531 0084 20 and 531 0103 20.

This Service Information sheet shows the visual features of the previous version (Figure 1 left) and the new version (Figure 1 right).

During the transition period, we may have mixed stocks of the old and new types.

The two versions differ only in their appearance. Both comply with the technical specifications and can be used without restrictions.

Observe the specifications of the vehicle manufacturer!

Spare parts and technical information can be found under www.schaeffler-aftermarket.com or www.RepXpert.com.

Phone: +44 (0) 14 32 264 264*
 Fax: +44 (0) 14 32 375 760
 info@luk-as.co.uk
 www.schaeffler-aftermarket.com

* Calls from within the UK 08457 001100

SCHAEFFLER
 AUTOMOTIVE AFTERMARKET

