

VISUAL DIFFERENCES BETWEEN OVER-RUNNING ALTERNATOR PULLEYS 59977 AND 57441

TECHNICAL INFO NO. 1048

VEHICLE MANUFACTURER / MODELS:

Honda | Accord VIII, Accord IX, Civic VIII CR-V II,
CR-V III, FR-V

APPLIES TO ENGINES:

2.2 i-CTDi, 2.2 i-DTEC

APPLIES TO PART NO.:

RUVILLE-No.	OE-No.:
59977	31141-RBD-E02
57441	31141-RL0-G01

IMPORTANT NOTE!

The over-running alternator pulleys fully comply with the technical requirements and only differ in their appearance.

Note the specifications of the vehicle manufacturer!



Image 1: Over-running alternator pulley 59977



Image 2: Over-running alternator pulley 57441

Two different over-running alternator pulley versions may be installed in the models mentioned above.

Image 1 shows the production version (left) and the aftermarket version (right) of over-running alternator pulley 59977.

Image 2 shows the production version (left) and the aftermarket version (right) of overrunning alternator pulley 57441.



INFORMATION

Corresponding spare parts can be found in our online catalogue at www.ruville.de. Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.