

# DESIGN CHANGE

## AFFECTING TENSIONING PULLEY 55973

### TECHNICAL INFO NO. 1088

#### VEHICLE MANUFACTURER / MODELS:

<b>Citroen</b>	C4, C5, C8, Jumpy
<b>Fiat</b>	Scudo, Ulysse
<b>Ford</b>	Focus C-Max, C-Max, Focus II, Galaxy, Kuga, Mondeo IV, S-Max
<b>Lancia</b>	Phedra
<b>Peugeot</b>	307, 308, 407, 508, 607, 807, Expert
<b>Volvo</b>	C30, S40, V40, V50, C70, V70, S80

#### APPLIES TO ENGINES:

2.0 HDI, 2.0 D Multijet, 2.0 JTD, 2.0 TDCi, 2.0 TDI

#### APPLIES TO PART NO.:

	<b>RUVILLE-No.</b>	<b>OE-No.</b>
<b>Citroen</b>	55973	0829.A4
<b>Fiat</b>	55973	9464640480
<b>Ford</b>	55973	1231975 / 3M5Q-6B217-AA
<b>Lancia</b>	55973	9464640480
<b>Peugeot</b>	55973	0829.A4
<b>Volvo</b>	55973	8653651

#### TENSIONING PULLEY IS PART OF FOLLOWING KITS:

5597370	Timing belt kit
5597350	Pulley kit
55973701	Waterpump kit

#### IMPORTANT NOTE!

Note the specifications of the vehicle manufacturer!



Figure 1: Previous design



Figure 2: New design



Figure 3: Previous design



Figure 4: New design

As part of our continuous efforts to improve our products, modifications have been made to the tensioning pulley with part number 55973.

This technical Information sheet shows the visual features of the previous version (Figures 1 and 3) and the new version (Figures 2 and 4).

During the changeover period, it is possible for mixed stocks of both versions to occur. Both versions comply with the technical requirements and can be used without restrictions for the vehicles stated in the catalogues.



#### INFORMATION

Corresponding spare parts can be found in our online catalogue at [www.ruville.de](http://www.ruville.de). Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.