

CHANGE AFFECTING HYDRAULIC BUCKET TAPPET

TECHNICAL INFO NO. 1113

VEHICLE MANUFACTURER / MODELS:

Alfa	145, 146, 147, 155, 156, 166, GT, GTV, Spider
Fiat	Barchetta, Brava, Bravo I, Coupe, Doblo, Marea, Multipla, Palio, Punto, Siena, Stilo
Lancia	Kappa, Lybra, Thesis
Rover	100, 200, 400, 600, 800, Carbrio

APPLIES TO ENGINES:

1.6, 1.6 16V, 1.7 T.S. 16V, 1.8 16V, 2.0, 2.0 16V, 2.0 20V, 2.4 20V

APPLIES TO PART NO.:

RUVILLE-No.	OE-No.
265801	Fiat: 464103078
265805	73503122

IMPORTANT NOTE!

The new hydraulic bucket tappet is 2 mm higher. Although the installation height is now different, the new bucket tappet can be fitted in the specified engines without any problems. The two versions do not differ in terms of their technical function.

Note the specifications of the vehicle manufacturer!

The vehicle manufacturers for the models specified above have changed the installation height of the hydraulic bucket tappet. Accordingly, RUVILLE is offering a modified version in the aftermarket.



Figure 1: Hydraulic bucket tappet: left: old version, right: new version



Figure 2: Hydraulic bucket tappet, left: old version, right: new version



INFORMATION

Corresponding spare parts can be found in our online catalogue at www.ruville.de. Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.