

VISUAL DIFFERENCES IN FINGER FOLLOWER 235414

TECHNICAL INFO NO. 1123

VEHICLE MANUFACTURER / MODELS:

Audi	A3
Seat	Leon, Mii
Škoda	Citigo, Octavia
VW	Golf VII, Jetta III, Up

APPLIES TO ENGINES:

1.0, 1.0 EcoFuel, 1.2 TSI, 1.4 TSI, 1.4 TSI Hybrid

APPLIES TO PART NO.:

RUVILLE-No.	OE-No.
235414	04E 109411 H 04E 109411 J

IMPORTANT NOTE!

Always replace in sets!

As a basic measure, all finger followers in the engine must be replaced at the same time. To avoid multiple repairs and unnecessary costs, it is also advisable to replace the finger follower and the valve clearance compensation element at the same time.

Observe all information provided by the manufacturer!

Two different types of finger follower (image 1 and image 2) can be installed in the engines mentioned above. They only differ from one another in terms of visual appearance, and both fully meet the technical requirements.

For this reason, RUVILLE only offers the type of finger follower in image 1 with the item number 235414.



Figure 1: Version 1



Figure 2: Version 2



INFORMATION

Corresponding spare parts can be found in our online catalogue at www.ruville.de. Where reference is made to the spare parts numbers of the vehicle manufacturers, this is only for the purposes of comparison.